





R100 Plus

1-Speed, 120 Volt, 1 Phase, 60Hz., 3/4 HP
1725 RPM, 7 Amps



**Click on Red Dot
OR
Call us for help
800-465-6060**



ACCESSORIES

